



### **Home Test for Checking for A Leak**

There is a easy way to check for evaporative loss.

1. Take a bucket and set it on the top step.
2. weigh down the bucket
3. make a mark at the water level of the pool and fill the bucket to that level.

If it is evaporation, the pool should lose the same amount as the bucket.

If the loses are different.

1. Mark the level and run the pump for 24 hours.
2. Measure the loss.
3. Refill and leave the pump off for 24 hours.
4. Measure the loss again.

This test can help determine the source of the leak (return line, suction line, or vessel).